

WIRE GAUGE	OHMS PER 1000'
0000	0.05
000	0.06
00	0.08
0	0.10
2	0.16
4	0.25
6	0.40
8	0.64
10	1.02
12	1.62
14	2.58
16	4.10
18	6.25
22	